


Ενδεικτικές θέσεις παρεμβάσεων

Επισκευή δαπέδου σκυροδέματος με έτοιμα επισκευαστικά κονιάματα.	1	2	7	9	10	11	13	15	16	17
	18	19	19α	20	20α	21	21α	21β	21γ	21δ
	22	24	25α	25β	26	27	29	30	31	32
	33	35	36	37	38	39	45	47	48	49
	50	53	55	56	57	60	62	63	64	65
	66	67	68							
Διάστρωση οπλισμένου σκυροδέματος C16/20	1	2	7	13						
Πλακοστρώσεις με Βοτσαλόπλακες	9	10	18	22	27	64				
Καθαιρέσεις ζαρντινιρών	31	40	52	58	61					
Επισκευή Ζαρντινιερών	4	8	14	23						
Ανακατασκευή σε ράμπες ΑμεΑ	3	6	12	16						

Ο Συντάκτης



Φώτης Μάραντος
Πολιτικός Μηχανικός



2

10

9

8

7

6

5

4

3

2

1

Santitas



11

12

13

14

15

16

17

ZB

ZB



2

23

18

19

19a

20

20a


24

Maverick

PHOTOGRAPHY



PHOTOGRAPH





25

26

27


29


28

30

26

27





78

34


35

36

37

79

W. Westenberg



2

38

39

40

40

41

42

43

44

45

29

210



Z10

Z11

47

46

49

48

49

50





2

212

51

52

53

52

211





56

55

54

Naxos Road

© 2014 Google

25

512



Z

Z14

58

57

Z13



Z16


62

61

60

Z15





2

Z17

68

67

Navaritou

66

65

64

63

Z16



